// WATER ANALYSIS REPORT //

WATER TESTING LABORATORY, PUBLIC HEALTH ENGINEERING SUB DIVISION KHANDWA

1. Particulars of Sender:

2. Particulars of Sample:

Principal

Place Where sample is collected -

Holy Spirit Convent Higher Secondary School Khandwa

01Holy Spirit Convent Higher Secondary

School Khandwa - D/W

3.Senders Letter NO: - 1059 Date: - 06.07.2023

4.MR NO.-17/1357

Date:-06.07.2023

5.Date of sample Receipt :- 06.07.2023

6.Date of Testing :- 06.07.2023

7. Nature of study :- Physical /Chemical/Bacteriological test

8. Water Sample Isn't Collected by Laboratory

7. Nature of study :- Physical /Chemical/Bacteriological test 8. Water Sample Isn't Collected by Laboratory						
	Characteristics	Units	Appendix 23(a)	as per		
S.No.			manual on Water Supply		RESULT OBTAINED	
			Treatment prepared published			
			by BIS Standard:IS			
			10500:2012			
			Requirment	Permissible		
			(Desirable	Limit in the		
			Limt)	Absence of		
				Alternate	Sample No 01	
1	2	3	4	Source 5	Sample No 01	
1	PHYSICAL - TEST					
1	Turbidity	NTU	1	5	2.0	
	Colour	Hazen	5	15	-	
CHEMICAL - TEST						
2	PH	pH Scale	6.5 to 8.5	No relaxation		
	10.10.10				7.31	
	TDS	Mg/L	500	2000	364	
5	Chlorides	Mg/L	250	1000	47	
6	Nitrates	Mg/L	45	45	-	
7	Total Hardness (as caco3)	Mg/L	200	600	206	
8	Calcium	Mg/L	75	200	44	
9	Magnesium	Mg/L	30	100	23	
10	Total Alkalinity (as CaCO3)	Mg/L	200	600	190	
11	Iron (as Fe)	Mg/L	1.0	1.0	0.1	
12	Fluoride (as F)	Mg/L	1.0	1.5	0.4	
13	Sulphate (as SO4)	Mg/L	200	400	9.0	
14	Residual Chlorine	PPM	0.2	1	-	
BACTERIOLOGICAL - TEST						
15	Faecal Coliform	per/	100 ml		Nill	
13	Taccar comorni	100 ml				

Remark: -Please disinfection of drinking water is necessary with bleaching powder or sodium hypochloride before using.

NOTE: The figurers indicated under column "Desirable Limit" in table given above limits up to which the water is generally acceptable to the consumer.

The figures is exces of those mentioned under "Permissible Limit" render the water acceptable but still may be tolerated in the absence of alternative and better source bellow the limits indicated under column "Permissible Limit" above, beyond which the supply have to be rejected.

ANALYST

LABORATORY INCHARGE Water Testing Laboratory

ASSISTANT ENGINEER PHE SUB DIVISION KHANDWA

Water Testing Laboratory

APPENDIX - VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARYCONDITION CERTIFICATE.

No. 1039 NIGAM KNW

Date: 07/07/2023

It is certified that an inspection team headed by MR. AJAY PATEL

SWASTH NIRTKSHAK (Name of Officers

with designation) from MUNICIPAL CORPORATION, KNW (Name of

Department/Office) inspected the HOLY SPIRIT CONVENT SCHOOL

VATSALA VIHAR, CIVIL LINES, KHANDWA (Name & Address of

the School) on 05/07/2023 and found that the HOLY SPIRIT CONVENT

SCHOOL, VATSALA VIHAR, KHANDWA (M.P.) (Name of school) has safe

drinking water facilities for the students and members of staff of the institution and is

maintaining the hygienic sanitation condition in the school building & the campus as per the

norms prescribed by the Central/State/U.T Govt.

The above valid for a period of 3. YEARS...

Signature with Seal : ्रार पालिक निगम, अपन्य

Name: MR. AJAY PATEL

Designation: SWASTH NIRIKSHAK.

To

HOLY SPIRIT CONVENT SCHOOL, VATSALA VIHAR, CIVIL LINES, KHANDWA (M.P.)

(Name & Address of the Institution)